Constructing Control Charts with Average Run Length Constraints

Robert B. Davis
Miami University

Abstract

In many statistics courses for engineering majors, students learn how to construct control charts for monitoring quality levels of manufacturing processes. However, the students generally just learn how to use the standard “three-sigma” approach, where control limits are established at three standard deviations above and below the average value. Often, no details are given as to how the sample size and control limit choices ultimately determine the performance of the control chart. In this paper, we will demonstrate how with some basic knowledge of geometric, normal, and chi-square random variables, a student can learn to construct $\bar{X}$ and S control charts that will have specified properties in terms of performance. In evaluating control charts, one is usually concerned with the false alarm rate (how frequently does the chart erroneously signal if the monitored process is on target?) and the detection rate (how quickly does the chart signal if the monitored process is not on target?). Using the simple tools proposed in this paper, the designer of a control chart can determine the sample size and control limits required to establish a desired false alarm rate and a desired detection rate for some specific out-of-control state. Teaching the process control material in this fashion connects the probability material learned in the early part of the course with countless real-world applications, making the probability material much more accessible and relevant to the students.

I. Introduction

In many statistics courses for engineering majors, students learn how to construct control charts for monitoring quality levels of manufacturing processes. However, the students generally just learn how to use the standard “three-sigma” approach, where control limits are established at three standard deviations above and below the average value. Often, no details are given as to how the sample size and control limit choices ultimately determine the performance of the control chart. In this paper, we will demonstrate how with some basic knowledge of geometric, normal, and chi-squared random variables, a student can learn to construct $\bar{X}$ and S control charts that will have specified properties in terms of performance. In evaluating control charts, one is usually concerned with the false alarm rate (how frequently does the chart erroneously signal if

the monitored process is performing properly?) and the detection rate (how quickly does the chart signal if the monitored process is not performing properly?). Using the simple tools proposed in this paper, a student can design a control chart with a desired false alarm rate and a desired detection rate for some specific out-of-control state. Teaching control chart material in this fashion connects the probability material learned earlier in the course with countless real-world applications, making the probability material much more accessible and relevant to the students.

II. Control Chart Basics

Statistical process control (SPC) is a common application of statistics in manufacturing. The goal of SPC is to monitor a process to make sure it is performing properly (i.e. the process is “in control”). An SPC technique should provide an indication of trouble (a “signal”) as soon as possible in the event that the process begins performing improperly (i.e., the process is “out of control”). In SPC, output from some process is periodically sampled and some trait is measured. The resulting measurements are then subjected to some algorithm that indicates whether or not there is reason to believe that the process is out of control. For example, suppose we want some individual trait of our items to be as close to 80 as possible. In SPC, we might sample five items per hour and compute their average measurement; as long as the resulting average is between 79.8 and 80.2, perhaps we have no reason to believe that the process is out of control. If a sample mean falls outside of the interval, then a signal is generated.

The most common SPC tool is the Shewhart $\bar{X}$ control chart. This chart is used to monitor process averages. When using a Shewhart chart, one must first have either a desired process mean or an estimate of the process mean when the process is performing properly. This value will be denoted by μ_0 . One must also have an estimate of the standard deviation of the process. This value will be denoted by σ . At some fixed time interval, a sample of n items is inspected and the sample average $\bar{X}$ of these items is computed. The value of $\bar{X}$ is plotted on the vertical axis of the chart, with the horizontal axis corresponding to time. Control limits are placed on the chart at $\mu_0 \pm k\sigma/\sqrt{n}$, where k is some constant (usually 3). When a sample mean falls inside the control limits, it is assumed that the process is in control. However, if a sample mean falls outside the control limits, an out-of-control signal is generated. The control limits are generally placed far enough away from the central value of μ_0 as to make it very unlikely that a signal will be produced unless the process has genuinely gone out of control. For example, if $\bar{X}$ follows a normal distribution, $k = 1$ would be disastrous – almost a third of our sample means would fall beyond the control limits even when the process was in control, meaning that we would have a high frequency of false alarms with such a chart.

III. Evaluating Control Chart Performance

Any sequence of samples that leads to an out-of-control signal is called a “run.” The number of samples that is taken during a run is called the “run length.” Clearly, the run length is of paramount importance in evaluating how well a control chart performs. Because run length can vary from run to run, even if the process mean is held constant, statisticians generally focus on the average run length (ARL) that would be obtained for any specific set of underlying parameter values. If the process is in control, a perfect control chart would never generate a signal – thus, the ARL would be infinitely large. If the process is out of control, a quick signal is desired – an ARL of 1 would be ideal.

Of course, reconciling both of these demands is impossible. In order to satisfy the first requirement we would need the control limits to be extremely far away from the central value; in order to satisfy the second requirement we would need the control limits to be indistinguishable from the central value. However, if we are more reasonable in our demands and can use any sample size, charts can be designed to meet ARL constraints. For example, it is possible to design a chart with $ARL = 500$ if the true process mean is 80 and $ARL = 5$ if the true process mean is 81. In designing a Shewhart chart, two variables (k and n) are specified. The fact that we are choosing values for two quantities means that if two ARL constraints are stated, a Shewhart chart can be designed to meet them.

IV. The Typical Textbook Approach

The typical statistics textbook for engineering students presents tables of constants that are useful in building Shewhart charts. The approach taken in most texts is summarized below:

- (1) The engineer has some large number of repeated samples of process output. The samples are all of size n .
- (2) For each sample, the engineer computes $\bar{X}$ and some measure of spread (either standard deviation $S = \sqrt{\sum (x - \bar{x})^2 / (n - 1)}$ or range R).
- (3) The engineer computes the average $\bar{\bar{X}}$ of the $\bar{X}$ values, as well as the average of the chosen measure of spread (that is, either $\bar{S}$ or $\bar{R}$).
- (4) The engineer then refers to a table of values that includes multiplicative constants needed for control limit computation. These constants are functions of the size of the repeated samples.
- (5) The engineer computes the control limits. The chart is now ready for use.

We will look at an example and refer specifically to Walpole et. al.¹ to construct an $\bar{X}$ chart. In that text, formulas for the $\bar{X}$ chart control limits are given on p. 632 as $\bar{\bar{X}} \pm A_2 \bar{R}$, where the value of A_2 is obtained from a table on p. 710. Suppose we have taken numerous samples of size ten from a process and obtained $\bar{\bar{X}} = 14.4$ and $\bar{R} = 2.9$. The value of A_2 from the table is 0.308.

Thus, we would compute control of $14.4 \pm .308(2.9) = 14.4 \pm .893$, or 13.507 and 15.293. In the future, any sample mean based on a sample of size ten would be compared against these control limits to determine whether or not we have evidence of a problem with the process. Details will be omitted here, but note that these limits are unbiased estimators of $\mu_0 \pm 3\sigma/\sqrt{n}$. That is, the A_2 values are the ratios needed so that the expected value of $A_2 \bar{R}$ is $3\sigma/\sqrt{n}$. Thus, students are taught how to construct Shewhart charts with $k = 3$.

As mentioned previously, this approach is the standard method taught in such courses. See, for example, Devore & Farnum², Larsen et.al.³, or virtually any other statistics textbook used in undergraduate general statistics courses for engineering students.

Unfortunately, due to space and time considerations in the textbooks and courses, this is where the discussion of control charts usually ends. There is no treatment of run lengths, ARL values, or control chart design. Not all engineering students go on to take a course in quality control, so this may be the only place to expose them to such material in their undergraduate educations. With just one or two additional lectures, the students can emerge with a much better knowledge of control chart issues, and can design $\bar{X}$ and S charts with ARL constraints. Additionally, the topic allows the class to revisit several important distributions (the geometric, the normal, and the chi-squared) and further emphasizes the importance of sample size in virtually every statistical problem.

V. Shewhart Charts and the Geometric Distribution

Recall that in a Shewhart control chart scenario, samples are taken at fixed time intervals. If a sample value falls outside the control limits, a signal is generated; the run length is the number of samples required to generate a signal.

One of the discrete distributions usually covered in this type of statistics course is the geometric distribution. The geometric distribution governs a random variable that is the number of trials it takes to obtain our first success, given that the trials are identical and independent and that each trial can result in only one of two possible outcomes (success or failure). Suppose p is the probability of success on a given trial, and let X be the trial on which we observe our first success. Then X is a geometric random variable with $P[X = x] = (1-p)^{x-1}p$, $x = 0, 1, 2, \dots$. The expected value of a geometric random variable is $E[X] = 1/p$.

Let p be the probability of a signal being generated on a given sample when using a Shewhart chart. The run length associated with the control chart is a geometric random variable – because each sample is independent of other samples, and each either generates a signal (success) or not. The ARL for a Shewhart chart, then, is simply $1/p$. Thus, if we want to constrain the ARL in some way, we can do so by choosing control limits that yield appropriate signal probabilities on

any given sample.

VI. Designing $\bar{X}$ Charts with Two ARL Constraints

As previously mentioned, in general we would like a very large ARL when a process is in control and a very small ARL when a process is out of control. If we formulate two ARL constraints, we can construct a system of two simultaneous equations that both involve k and n as described below.

Let μ_0 be the desired process mean, and suppose we would like to obtain an ARL value of ARL_0 when the process mean is μ_0 . Suppose $\mu_1 > \mu_0$ is a process mean value that we deem undesirable, and that we would like to obtain an ARL value of ARL_1 when the process mean is μ_1 . Suppose further than individual observations have a standard deviation of σ . Note that if the individual items are normally distributed (a common assumption in this scenario), then $\bar{X}$ will be normally distributed with variance σ^2/n .

Because the probability of a signal is the reciprocal of the ARL (from the discussion of the geometric distribution given above), let $p_0 = [ARL_0]^{-1}$ and let $p_1 = [ARL_1]^{-1}$. Because $\bar{X}$ is normally distributed, we can construct the following equations governing the Upper Control Limit (UCL) of the Shewhart chart:

$$UCL = \mu_0 + k_0\sigma/\sqrt{n}, \text{ where } k_0 = Z(1 - p_0/2) \quad (1)$$

$$UCL = \mu_1 + k_1\sigma/\sqrt{n}, \text{ where } k_1 = Z(1 - p_1) \quad (2)$$

Here, $Z(p)$ is the inverse of the standard normal CDF; for example, $Z(.975) = 1.960$. By setting these two expressions for UCL equal to one another after filling in k_0 and k_1 , we generate an equation in which sample size n is the only unknown. After solving for the sample size, we can substitute n back into either equation to produce an appropriate UCL value. The Lower Control Limit (LCL) will be symmetric with respect to the central value of μ_0 .

As an example, consider the following case. Suppose we have a desired process mean of 80, and we would like a Shewhart chart with an ARL no lower than 500 when in control. However, if the process mean shifts to 81, we would like an ARL no higher than 5. Suppose further that the standard deviation of individual items is $\sigma = 1.4$. Using the inverse normal distribution routine on the Texas Instruments TI-83 graphing calculator (many students have this model) yields $k_0 = Z(.999) = 3.09$ and $k_1 = Z(.8) = 0.84$. Equations (1) and (2) respectively become:

$$UCL = 80 + 3.09(1.4)/\sqrt{n} \text{ and} \quad (3)$$

$$UCL = 81 + 0.84(1.4)/\sqrt{n}. \quad (4)$$

Solving these equations for n yields $n = 3.15^2 = 9.925$. Because sample size must be an integer, this means that with a sample size of $n = 10$ we will satisfy both constraints. Now, (3) yields $UCL = 81.368$ and (4) yields $UCL = 81.372$. Thus, we satisfy both constraints with an upper control limit of 81.37. The lower control limit must be 78.63, due to symmetry. (It is easy to show that such a chart will yield an ARL of 507.2 when the process mean is 80 and an ARL of 4.96 when the process mean is 81 – asking students to demonstrate this will give them a bit more practice with the basics of using the normal distribution).

Note that without loss of generality, one could use an out-of-control mean value $\mu_2 < \mu_0$. Due to the symmetry of the normal distribution, let $\mu_1 = \mu_0 + (\mu_0 - \mu_2)$ and proceed as described above.

VII. Designing S Charts with Two Average Run Length Constraints

The standard approach taken by textbooks for the design of S charts is similar to the approach used in designing $\bar{X}$ charts. A large amount of data is collected, in separate samples of identical sample size. For each sample, the value of S is computed; then, the values are averaged, yielding the value of $\bar{S}$. Afterwards, coefficients obtained from a table are multiplied by $\bar{S}$ in order to determine lower and upper control limits. These control limits are unbiased estimates of three-sigma limits for any individual S value based on the appropriate sample size.

Again, viewing run length as a geometric random variable allows us to use the sampling distribution of S^2 to design a control chart for S that will have some desired ARL properties. In particular, if the individual items being sampled follow a normal distribution then it is a well-known result that a chi-squared distribution governs the behavior of S . More specifically,

$$(n-1) S^2 / \sigma^2 \sim \chi^2 \text{ with } n-1 \text{ degrees of freedom,} \quad (5)$$

where σ is the standard deviation of the individual observations. In the case of designing S charts, we will consider only one-sided charts in which we are trying to make sure that the variance of the items does not exceed some target value. This is often the case in manufacturing applications, where the goal is to produce many identical units. Thus, we will only concern ourselves with an upper control limit (UCL).

Suppose the target standard deviation for a process is σ_0 , and that we require a chart to have an ARL of at least ARL_0 when the process is running at the target value. Further, suppose that if the standard deviation of the process increases to σ_1 , we require that the chart have an ARL of at most ARL_1 . As before, let $p_0 = (ARL_0)^{-1}$ and let $p_1 = (ARL_1)^{-1}$.

The ARL_0 requirement means that we need $P[S > UCL] < p_0$ when the true process standard deviation is σ_0 . This is identical to the following statement:

$$P[(n-1)S^2/\sigma_0^2 > (n-1)UCL^2/\sigma_0^2] < p_0. \quad (6)$$

Working similarly with the ARL_1 requirement yields

$$P[(n-1)S^2/\sigma_1^2 > (n-1)UCL^2/\sigma_1^2] > p_1. \quad (7)$$

Now, consider the sampling distribution result given earlier. Let $\chi^2(p)$ represent the inverse chi-square cumulative distribution function with $n-1$ degrees of freedom. From (6), we obtain:

$$(n-1)UCL^2/\sigma_0^2 > \chi^2(1-p_0) \rightarrow UCL^2 > \chi^2(1-p_0)\sigma_0^2/(n-1). \quad (8)$$

Similarly from (7), we obtain:

$$(n-1)UCL^2/\sigma_1^2 < \chi^2(1-p_1) \rightarrow UCL^2 < \chi^2(1-p_1)\sigma_1^2/(n-1). \quad (9)$$

Thus, in order to meet both constraints we require the sample size n to be large enough so that this inequality is satisfied:

$$\chi^2(1-p_1)\sigma_1^2/(n-1) > \chi^2(1-p_0)\sigma_0^2/(n-1). \quad (10)$$

A bit more simple algebra yields:

$$(\sigma_1/\sigma_0)^2 > \chi^2(1-p_0)/\chi^2(1-p_1). \quad (11)$$

In order to design the chart appropriately, we must use the inverse χ^2 cumulative distribution function, using different values of n until we find the smallest value of n that satisfies (11). The UCL can then be any number between the positive square roots of the two sides of inequality (10) and the chart will perform as desired.

While the $\bar{X}$ chart can be designed easily enough with most standard normal tables, the S chart is more difficult to design by hand because χ^2 CDF tables tend to be restricted to certain critical values. Also, while the Texas Instruments TI-83 calculator has a χ^2 CDF built in, it does not have the inverse CDF. Thus, when teaching this material it is best if the students have access to some statistical software such as Minitab.

As an example, suppose we are dealing with a normally distributed quality characteristic. We would like for our S chart to have an ARL of at least 250 when $\sigma = 8$; however, if $\sigma = 12$, we require the chart to have an ARL of at most 2.5. Thus, $p_0 = 1/250 = .004$ and $p_1 = 1/2.5 = .4$. We need to find the smallest value of n so that $(12/8)^2 > \chi^2(.996)/\chi^2(.6)$, where the χ^2 distribution has

$n-1$ degrees of freedom. Starting at $n=2$ and incrementing n as needed, eventually when we have 13 degrees of freedom we find $\chi^2(.996) = 30.4905$ and $\chi^2(.6) = 13.6356$. These values yield a ratio of $2.236 < (12/8)^2$. This means we require a sample size of fourteen items (so that we obtain thirteen degrees of freedom). Inequality (10) suggests that we must have $12.251819 < UCL < 12.289853$; an upper control limit of 12.27 could be chosen, as it is nearly halfway in between the two sides of the inequality and has as few decimal points as is possible to still fall between the two sides. A computer program for this algorithm has been previously published⁴, but even without the program the procedure is fairly simple if a χ^2 inverse CDF routine is readily available.

VIII. Conclusions

Many standard textbooks for undergraduate statistics courses geared towards engineering students are limited in terms of the quality control concepts they present. This is understandable in some sense, as these courses need to communicate a great deal of information in a single semester. However, statistical process control, which is an important aspect of engineering, should be given more emphasis when possible.

The two techniques presented in this paper have several advantages in terms of presenting them in such classes. Not only do they give students a better understanding of control chart issues, they are based on probability theory that is learned earlier in the course. Re-emphasizing some basic probability distributions like the geometric, in a way that demonstrates the applicability of the distributions to important real-world problems, is an effective way to address the “why did we learn that material anyway?” questions that students will inevitably ask during the semester. The techniques are also easy to teach because the algebra involved is rather elementary, allowing the students to focus in on the important concepts instead of getting lost in complicated details. It should be possible to cover these two techniques in only one or two class meetings, so that a major time commitment to teach this material is not required.

Bibliography

1. Walpole, Myers, Myers, & Ye. *Probability and Statistics for Engineers and Scientists* (7th edition). Upper Saddle River, NJ: Prentice-Hall Inc (2002).
2. Devore, J. & Farnum, N. *Applied Statistics for Engineers and Scientists*. Pacific Grove, CA: Duxbury Press (1999).
3. Larsen, Marx, and Cooil. *Statistics for Applied Problem Solving and Decision Making*. Pacific Grove, CA: Duxbury Press (1997).
4. Davis, R.B. “Designing S-Charts With Two Average Run Length Constraints.” *Journal of Quality Technology* 31:2, April 1999, pp. 246-248.

ROBERT B. DAVIS

Robert B. Davis is currently an Associate Professor at Miami University. He received his B.S. in Computer Science from Loyola University in New Orleans and his M.S. and Ph.D. in Statistics from The University of Louisiana - Lafayette. His research interests include Statistical Process Control, Environmental Statistics, Game Theory, and Sabermetrics.