Studies on Stress Concentration Using Experimental and Numerical Methods

ABSTRACT

The experimental and numerical studies were conducted to investigate the stress concentration around a circular cutout in an isotropic material. Test specimens with circular holes were loaded in tension and bending. The tension test specimen was loaded in an Instron test machine. By mounting a set of strain gages orthogonal to the applied loading direction, the students performed the longitudinal strain measurements in the vicinity of the hole. The strains obtained by the series of strain gages placed at varying distances from the hole were extrapolated to the edge of the hole to determine the peak stress at the hole. These peak stresses were divided by the corresponding nominal far field stresses to obtain the stress concentration factors for specimen loaded in tension.

The bending case was investigated with a cantilever beam with a hole at its mid span. The Flexor setup by Vishay Instruments was used for this purpose. The hole was located in such a way that the nominal stress at the fixed end was the same as the one at the location of the hole. Strain gages were placed at varying distances from the edge of the hole, one being directly adjacent to the edge. Known amounts of load were applied at the free end of the beam. The peak strains at the hole were extrapolated from the strain gage readings similar to what was done for the tension case. The stress concentration factor is the peak strain at the hole divided by the nominal strain at the same location.

The experimental results on stress concentrations were compared with finite element solutions performed on the specimen geometries and loadings similar to the ones used in the experiments. A mesh of quadrilateral elements was used to model both the tensile bar and the cantilevered beam specimens with holes. The tensile and the bend specimen geometry and loadings were used to calculate the stress concentration factors. The two dimensional finite element simulations were performed using ANSYS general-purpose computer program. The nodal stresses were used to calculate the stress concentration factors.

The stress concentration factors obtained by the experimental and numerical methods were compared with the corresponding closed form solutions.

INTRODUCTION

This study constitutes a laboratory component of the strength of materials courses taught to both engineering and engineering technology students. It is important that engineering students learn the detrimental effects of stress raisers such as notches, holes, and sharp corners in machine members. Such discontinuities can cause a large rise in stress above the nominal value. This topic is introduced in the strength of materials course in the design of a stepped shaft with keyways subjected to bending, torsion, as well as axial loads. The nominal axial stress, the bending stress, and the shear stress due to torsion in the shaft are each multiplied by the corresponding stress concentration factors obtained from the literature. This approach does not generally present a convincing argument to the engineering student so there is a need to provide a different perspective to reinforce the concept of stress concentration. This issue is addressed through an experimental method as well as a numerical method. The experimental method uses strain gages in which the actual strains and also stresses can be measured in the laboratory. The numerical method is based on a finite element solution. In a tensile specimen, a discontinuity

such as a through-the-thickness circular hole is a stress raiser, and its effect on the stress is through a stress concentration factor. Similarly, a circular hole drilled through a beam loaded in bending is also a stress raiser with its own stress concentration factor. In this study the analytical solutions to the stress concentration factors for both the tensile and cantilever specimens due to a circular hole have been compared with experimental and numerical methods.

First, the students are introduced to the concept of stress concentration factor and the analytical results of stress concentration factors for various test specimen geometries are outlined. Experimental studies on stress concentration factors are conducted for (a) bar with a hole in tension and (b) cantilever beam with hole in bending. Then the numerical solutions for the stress concentration factors for the test specimen geometries are conducted using finite element analyses.

STRESS CONCENTRATION FACTORS

Any physical discontinuity in a structural member or a sudden change in the geometric form of a part leads to a region of stress concentration. The abrupt change in cross sections cause the stress "flow lines" to crowd causing high stress concentration. To mitigate this phenomenon, smoother changes such as fillet radii are introduced in structural members that make the "flow lines" less crowded causing lower stress concentrations. The theoretical stress concentration factor, K_t is defined in terms of maximum (or peak) stress, σ_{max} and nominal (or average or farfield) stress, σ_{nom} as:

$$K_t = \frac{\sigma_{\max}}{\sigma_{nom}} \tag{1}$$

The theoretical stress concentration factor is a function of component geometry and loading. Analytical expressions for stress concentration factors may be found in Mott (2008), and Pilkey (1997). Stress concentration factor K_t for plate with hole under tension is shown as a function of the diameter to width ratio, d/b in Figure 1. For a plate with hole under bending the stress concentration factors as a function of the diameter to width ratio, d/b for various depth-to-thickness ratios d/h are shown in Figure 2. (Note that in the subsequent analysis we have used 't' for thickness) Both these figures have been obtained from Pilkey (1997). For the two specimen geometries used in the experiments, the experimental results as well as the results from the numerical solutions was compared with the corresponding analytical results displayed in Figures 1 and 2.



Figure 1: Stress Concentration Factor for a Plate with a Hole Loaded in Tension



Figure 2: Stress Concentration Factor for a Plate with a Hole Loaded in Bending At this stage the students were alerted to the fact that the stress concentration factor as given by equation (1) is a geometric property that is particularly relevant for brittle materials such as cast iron. For ductile materials such as mild steel, the stress concentration factor is very important for 3assessing fatigue life. Analytical values for two situations are shown in Figures 1 and 2.

PRELIMINARY EXPERIMENTAL STUDIES

In order to appreciate the stress flow lines around a discontinuity, such as a circular hole, two preliminary demonstrations are introduced. The first one is due to Crone (2002) in which a latex sheet containing a circular hole is used. Ruled parallel lines are drawn on the sheet orthogonal to the direction of pull. Initially the students are reminded that if we stretch a sheet without a hole, the lines stay parallel after the stretching. Because of the abrupt change in geometry at the hole, the lines curve around, leading to higher non-uniform stresses and strains. Figure 3 shows the latex sheet before (left) and after (right) the pull



Figure 3 Latex Sheet with a Hole in Tension showing the stress flow lines

The other demonstration is due to Xu (2008) and involves dog bone specimens made out of paper loaded in tension to failure. For a finite dog bone specimen with and without central holes, the students are able to notice that the specimen with a central hole fails at the edge due to



Figure 4: Paper Dog Bone Specimen Loaded in Tension to failure

high stress concentration as shown in Figure 4. The sketch on the left shows how a paper punch was used to punch the hole and the right side shows the stress flow as the specimen is pulled. The use of the stress flow concept is more effective in explaining the stress concentration

phenomenon. The tensile stress of the dog bone specimen is quite uniform at the far-field region and becomes very crowded when it encounters the hole, since the stresses cannot pass across the hole.

EXPERIMENTAL STUDIES ON A BAR WITH HOLE IN TENSION

A steel bar 0.125 in thick and 0.75 in wide i held between grips of an INSTRON machine with the length between the grips as 1.5 in. The bar contains a through thickness hole of 0.25 in diameter drilled through the center of the bar. The bar is pulled with a force of 30 lbs. The first step of analysis is to estimate the stress concentration factor using the analytical method. Far from the applied load area, stress is evenly distributed throughout the cross-section, which is called the nominal stress. From the definition of stress, this nominal stress can be calculated by ignoring the hole, as

$$\sigma_{nom} = \frac{P}{A} = \frac{30}{(0.125)(0.75 - 0.25)} = 480\,psi$$
 (2)

- Geometric factor = 0.25/0.75 = 0.33

- Stress concentration factor K_t is obtained from Figure 1, $K_t = 2.27$

In the experiment a set of strain gages is placed at varying distances from the edge of the hole, with one of the gages directly adjacent to the edge. Since the strain gages cannot be applied directly to the maximum stress location, remote stresses are used to determine the peak stress. A strain gage is placed very near to the grips, which provided information on nominal strain (and hence nominal stress) on the bar. The strains obtained by the series of strain gages placed at varying distances from the hole were extrapolated to the edge of the hole to determine the peak stress at the hole. These peak stresses were divided by the corresponding nominal far field stresses to obtain the stress concentration factors for specimen loaded in tension. The students found values that were reasonably close to the analytical value of 2.27.

EXPERIMENTAL STUDIES ON A CANTILEVER BEAM WITH HOLE

Figure 5 presents the geometrical details of the specimen used in the study and Figure 6 shows the set-up used (Vishay Measurement Group (1992)). In Figure 5, Location 1 (where the stress is σ_1) corresponds to the region adjacent to the clamped end. Location 2 (where the stress is Σ_2) corresponds to that of the hole. At Location 1, the stress distribution is uniform across the beam width. The bending stress at the location 1 is given by

$$\sigma_1 = \frac{M_1 c}{I_1} \tag{3}$$

At this location, the bending moment $M_1 = WL$ where *L* is the length of the beam span, and *W* is the applied load. If the beam width is *b* and the beam thickness is *t*, then the moment of inertia at location 1, $I_1 = (1/12) (b t^3)$. We also have c = t/2. Substituting these values in equation (1) we have,

$$\sigma_1 = \frac{6WL}{bt^2} \qquad (4)$$

At location 2, the bending moment $M_2 = W l$ where *l* is the distance of the hole center line from the free end where the load W is applied. With *d* as the hole diameter, the moment of inertia at location 2, $I_2 = (1/12) (b-d)(t^3)$. At location 2, the nominal bending stress is therefore given by,

$$\sigma_2 = \frac{M_2 c}{I_2} = \frac{6Wl}{(b-d)t^2}$$
(5)

The students noted that the bending stress σ_2 above is a nominal stress and contains no effect of stress concentration. The distance *l* was selected such that the nominal bending stresses at locations 1 and 2 are the same, that is $\sigma_1 = \sigma_2$, and thus from equations (4) and (5) it follows,

$$l = \left(\frac{b-d}{b}\right)L \tag{6}$$

If the maximum bending stress at the edge of the hole is Σ_2 , which contains the stress concentration effect, then the elastic stress concentration factor K_t at the hole is given by (noting that $\sigma_1 = \sigma_2$),

$$K_t = \frac{\Sigma_2}{\sigma_2} = \frac{\Sigma_1}{\sigma_1}$$
(7)

If the stresses are below the proportional limit, the stresses and the strains will be proportional. Therefore the stress concentration factor is also the strain concentration factors at the two locations. Thus the stress concentration factor K_t at the hole is the ratio of the maximum strain at location 2, E_2 to the nominal strain at location 2, ε_2 and with our particular choice of l, becomes the ratio of maximum strain at location 2 to the nominal strain at location 1, ε_l . Thus

$$K_t = \frac{E_2}{\varepsilon_1} \tag{8}$$

Figure 6 illustrates the experimental setup used in the study. The beam is loaded such that a nominal strain ε_1 reaches about 0.2%. This is important since the strain at the edge of the hole will be considerably higher and would produce yielding locally. The actual strains around the hole are measured by three small strain gages at varying distances from the edge of the hole in the transverse direction, with one gage placed directly on the edge of the hole.

The dimensions are, L = 254 mm, l = 178 mm, b = 25.4 mm, t = 6.35 mm, d = 6.35 mm The strains at the three locations are plotted and extrapolated to the edge of the hole to obtain an estimate of the peak strain at the hole. Then by determining the nominal strain at the clamped end and using the peak strain at the hole, the stress concentration factor is calculated using equation (6).



Figure 5: Dimensions of the Cantilever Beam with Strain Gage Locations



Figure 6: Flexor Setup

A large strain gage is placed at location 1, which we will call gage #4. The micrometer knob is adjusted such that the strain at gage #4 becomes 200 micro strains (maximum deflection). Three small strain gages are placed in location 2 at varying distances from the edge of the hole, with gage #3 placed 8mm, gage #2 placed 5 mm, and gage #1 placed 3mm from the center of the hole. For the imposed strain level at gage #4, the strains indicated by gage #3, gage #2,and gage#1 are recorded and subsequently plotted on a graph sheet at the location of the respective gage centerlines. A smooth curve is then drawn through the resulting data points to show the strain distribution in the vicinity of the hole. The estimate of the maximum strain at the edge of the circular hole, ε_{2max} is obtained by extrapolation. The nominal strain, ε_{1nom} is provided by gage #4 as 200 micro strains. The stress concentration factor K_t is then obtained by equation (3). The individual lab assignments are provided in Appendix A and Appendix B.

NUMERICAL STUDIES ON A BAR WITH HOLE IN TENSION

Bar is 38 mm x 19 mm x thickness = 3.2 mm. with a 16.3 mm diameter central hole. The students were instructed to use **symmetry** and model a **quadrant** of the bar. The problem was treated as a plate in plane stress. The geometry is created in ANSYS (ANSYS 12 (2009)). An eight node quadrilateral element is used to model the bar quadrant. Isotropic material properties for steel, namely the Young's modulus (207 GPa) and the Poisson's ratio (0.3) were introduced as inputs.



Figure 7: Application of Loads and Boundary Conditions on the Quadrant Model



Figure 8: Stress Profile for the X-Stress

Figure 7 shows the load applied and the applicable boundary conditions. Tensile load is applied as a uniform pressure of 100 psi applied on the vertical edge to the right. The bottom edge of the quadrant is input as a zero UY displacement and the vertical edge (left) is input as a zero UX displacement. Figure 8 shows the typical stress profile for the X-stress. The nominal stress and the peak stress information is used to obtain the stress concentration factor.

NUMERICAL STUDIES ON A CANTILEVER BEAM WITH HOLE IN BENDING

For this study a finite element model of the cantilever beam with the same dimensions as the specimen is prepared. One end of the beam is fixed for all displacements and rotations simulating the clamped end. On the free end a load of 14.7 N (1.5 kgf) is applied. Figure 11 shows the von-Mises nodal stresses and Figure 12 the corresponding strain results. The maximum stress was found to be 33.7 MPa, at the edge of the hole, and the nominal stress at that section is around 12 MPa. This gives a stress concentration factor of around 2.8 at the hole. The same value is obtained when the strains are compared in Figure 12. The analytical value obtained for a plate with d/h = 1.0 and d/t = 0.25 is obtained from Figure 2 as 1.85. The analytical method as shown is Figure 2 is for a pure bending, whereas the finite element method that correctly represents cantilever bending and that explains the discrepancy in the results. The experimental results are closer to the finite element solution results.



Figure 10: Finite Element Strain Results

PEDAGOGICAL CONSIDERATIONS

The activities described in this paper are accomplished as two separate modules in the laboratory session for the course strength of materials offered at a sophomore level. One is on tensile loading and the other was on cantilever bending. Both modules involve experimental and numerical efforts. The experimental methods use some preliminary studies to develop a feel for the stress flow, and are followed up with mounting strain gages at the appropriate locations in the specimen and acquiring expertise in instrumentation involving Wheat stone bridge. The finite element method is introduced as an alternative approach for modeling real-life structures. The students are able to visualize the effects of stress concentration around a circular hole for the case of both a bar in tension as well as a cantilever beam in bending. The preliminary studies (prior to the detailed experimental investigation using strain gages) provide an insight into the stress flow concept around discontinuities. The peak strain at the discontinuity (hole) is measured and compared with the nominal strain and the ratio, which measured the stress concentration factors were found to be close to the numerical solutions. For tensile specimen the results for numerical solution compare well with the analytical values of Figure 1. For cantilever

bending the corresponding results differ from the pure bending case shown in Figure 2. This brings home the point that proper modeling of the experimental situation is essential to predict correct response. This activity provides the students an intuitive appeal into the detrimental effect of stress raisers caused by discontinuities.

The finite element studies give a perspective of how the loads and stresses get distributed around discontinuities. The meshes are created automatically using ANSYS and the perspectives of the convergence of the solutions are also emphasized by mentioning that the mesh size refinement leads to progressively correct solutions. The color contours of the stresses around the hole demonstrate the gradient effects of the stresses around the discontinuity. The finite element method is introduced in the lab session only as a hands-on approach to solve a structural problem. No theoretical or numerical treatments associated with the finite element method are discussed. Instead, some of the modeling concepts involving symmetry features and boundary conditions are highlighted. As evidenced by the end of semester student evaluations, the students felt it was a good opportunity to get exposed to a general purpose finite element code such as ANSYS and its ability to solve problems involving stress concentrations associated with tension and bending situations.

BIBLIOGRAPHY

ANSYS 12 (2009), ANSYS, Inc, www.ansys.com

Crone, W. C. (2002), "Using an Advanced Mechanics of Materials Design Project to Enhance Learning in an Introductory Mechanics of Materials Course, *Proceedings of the 2002 American Society for Engineering Education Annual Conference and Exposition*, Session 2268.

Mott, R.L. (2008), *Applied Strength of Materials*, Fifth Edition, Pearson Prentice Hall, Upper Saddle River, New Jersey.

Pilkey, W. (1997), Peterson's Stress Concentration Factors, Wiley, New York.

Vishay Measurement Group (1992), Strain Measurement Technology, Raleigh, N.C.,

www.measurementsgroup.com.

Xu, L. R. (2008), "In Class Paper Demonstrations and Experiments fro Solid Mechanics Courses," *International Journal of Engineering Education*, Vol. 24, No. 3, pp. 540-544.

APPENDIX A Stress Concentration in a Tensile Specimen

OBJECTIVE:

In this experiment the stress concentration due to a center hole in a tensile specimen is investigated. If a discontinuity exists in a structural or machine element that interrupts the stress path, then the stress at the discontinuity may be significantly higher then the nominal stress on the section, thus leading to a stress concentration.

EQUIPMENT TO BE USED:

Instron Machine Vishay strain indicator Vishay switch and balance unit

TESTING PROCEDURE

An aluminum plate with a central circular hole will be subjected to a tensile load. Strain distributions are measured using strain gages attached to different positions on the plate. Local tangent strains are measured at five positions along the ligament. An additional, remotely located strain gauge, oriented parallel to the loading direction is used to obtain measurements of axial far field strain. An experimental measure of the strain concentration factor, can then be computed from the ratio of the maximum local strain at the notch root, to the remote axial strain, Note that for this geometry, with purely elastic behavior and uniaxial tensile stress states, the stress concentration factor equals the strain concentration factor.

- 1.) Install specimen between grips
- 2.) Zero strain indicator at the no load condition
- 3.) Load the plate in tension to a pressure of 500 psi
- 4.) Record data

DATA REQUIREMENTS:

The cross-sectional dimensions of the specimens must be measured. Care must be taken to avoid damage to strain gages.

APPENDIX B Stress Concentration in a Cantilever Specimen

OBJECTIVE:

The purpose of this experiment is to demonstrate the existence of stress and strain concentration in the vicinity of a geometric discontinuity in a cantilever beam, and to obtain an approximate measure of the stress concentration factor. In this case, the discontinuity is simply a circular hole, drilled through the beam on its centerline.

EQUIPMENT TO BE USED:

Vishay Flexor cantilever flexure frame Vishay P3 Strain Indicator

TESTING PROCEDURE

High-strength aluminum alloy beam, $1/4 \ge 1 \ge 1/2$ (3.2 $\le 25 \ge 318$ mm), outfitted with preinstalled strain gages and a $\frac{1}{4}$ " diameter stress concentration hole is used in the flexure frame. Three very small strain gages are placed at varying distances from the hole, with one directly adjacent to the edge. An additional, remotely located strain gauge, oriented parallel to the loading direction is used to obtain measurements of axial far field strain. An experimental measure of the strain concentration factor, can then be computed from the ratio of the maximum local strain at the notch root, to the remote axial strain, Note that for this geometry, with purely elastic behavior and uniaxial tensile stress states, the stress concentration factor equals the strain concentration factor.

1.) Install specimen in the flexure frame

2.) Load the beam till the nominal far-field strain is 200 micro strains

3.) Plot strains on a graph sheet at the locations of the gage centerlines, and draw a smooth curve.

4.) Extrapolate the data to the edge to obtain the peak strain

DATA ACQUISITION:

The gages are connected (via the flexor cable) to the strain indicator one at a time, first with the beam free, and then the beam deflected. An initial reference reading of the strain indicator readout is obtained for each gage with the beam free, and a final reading with the beam deflected. The differences in these two sets of readings gives the strains at the respective gage locations.